

DREW MARINE CYLINDER SAFETY SMART CHART



Do not lift by top valve or cap with slings, chains or magnets.



Never drop a cylinder.




Never store cylinders in extremely hot or cold temperatures.




Do not store with combustible material. Do not store acetylene and oxygen cylinders together.



Never use cylinders as rollers or supports.




Secure cylinders with rack clamps or chains. Never use rope.



Do not transfer gas from one cylinder to another.



Store in separate compartment or room. Always provide ventilation. Always have a fire extinguisher nearby.



Return empty cylinder with 1 bar of pressure.

Use only approved pressure regulator for gas.

Mark empty cylinder with MT.



Transport cylinders in upright position. Replace valve caps when cylinders are not in use.



Never hang electrode holder with electrode over cylinder or strike an arc on a cylinder.

Do not apply oil to any valve.

Never use a spanner or hammer to open or close the valve. Use hand pressure only.



Drew Marine.

333 CHURCH STREET, NAUGATUCK CT 06770 USA
1-973-526-5700 WWW.DREW-MARINE.COM

© 2021 DREW MARINE • REGISTERED TRADEMARK, TM TRADEMARK, DREW MARINE
CYLINDER SAFETY CHART 0521